	/EATHER CONSENT DECREE ATER TESTING FORM	Page 1 of 3				
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 09/02/2008				
Test Type: Smoke	Ground Condition: Dry: <b>X</b> Damp:_ Wet:_	Supervisor: E.R. Crew: 04				
Manhole ID: S19M047MH	Test ID: 1029-578	Notifications Made:X Residents, Fire, 311				
	oers, blower placement location, sandbag or iso d locations, defect locations and photograph nu	olation locations, street names, building addresses umbers)				
057DE	047 CHRISTIAN ST	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM					Page 2 of 3						
Sewershed: Low Lev Subsewershed: 44	vel	Company: REI/DRAYCO				Date: 09/02/2008					
Test Type: Smoke	е		round Co : X Damp				Supervisor: E.R. Crew: 04				
Manhole ID: S19M_047MH		Test ID: 1029-578					Notifications Made:X Residents, Fire, 311				
<b>Field Sketch:</b> (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)											
Defect Addres		Source Type	Location		Drain: Are	age	Severity		Photo Number		
1 2144 WILKENS AV	/E.	04	14	02	200		02		1029-578_OB01-01.jpg		
						-					
		<del>                                     </del>								$\exists$	
				1011.00							
Source Type		OB	SERVAT Location		DE2	Ş	Sector		Severity		
01 Main Sewer 10 MH F	rame 01	Paved C	Conc. 10		ved		Public	01	No Smoke		
02 Service Line 11 Storm	n Drain 02	Asphalt	11	Field/W		02	Private	02	Trace		
03 Cleanout 12 Catch			Other 12						Moderate		
04 Downspout 13 Storm 05 Area Drain 14 Storm				Golf Course Other				04	Major		
06 Dwy. Drain 15 Exca		Curb	. 14	J.(1)()	$-\parallel$						
07 Stair. Drain 16 Water	r Line 07	Yard - F									
08 Found. Drai 17 Tele.		Yard - B								$\Box$	
09 Bldg. Interio 18 Othe	r 09	Yard - S	ide								

## CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

## BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 578 Date: 09/02/2008 Basin: LL - 44 Manhole ID: S19M\_047MH Defect No: OB01 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: 2144 WILKENS AVE.

Source Type: 04 Downspout Sector: 02 Private

Location: 14 Other Severity: 02 Trace Drainage Area: 200

Comments: SMOKE APPEARS TO BE COMING FROM THE DOWNSPOUT AT THE ROOFLINE.

## **SMOKE TEST PHOTOGRAPHS**



Photograph No: OB01-01 Filename: 1029-578\_OB01-01.jpg